

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/15/2017

Submitted Date:

09/21/2017

Document Number:

685303760**FIELD INSPECTION FORM**Loc ID 306964 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 100178Name of Operator: D J SIMMONS INCAddress: P.O. BOX 1469City: FARMINGTON State: NM Zip: 87401**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**25 Number of Comments10 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
, Engineering		dnr_cogccengineering@state.co.us	
Leonard, Mike		mike.leonard@state.co.us	
Labowskie, Steve		steve.labowskie@state.co.us	COGCC

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
285440	WELL	PR	10/11/2007	GW	067-09196	CHEVILLAR 32-32	SI

General Comment:[See link at end of report for path to downloadable pictures.](#)[This inspection report does not alleviate requirement to complete open corrective action from previous inspection reports.](#)[Inspection completed to inventory risers/flowlines and check compliance with May 2017 Flowline NTO.](#)[Inspection report contains corrective action and comment.](#)

Location			
Lease Road:			
Type	Access		
comment:	Dirt and gravel access road.		
Corrective Action	L		Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Framed sign at tank battery.		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	Labels directly on tanks. Part of the NFPA label on produced water tank has peeled off and both tank are missing capacity label is gone.		
Corrective Action:	Install sign or label to comply with Rule 210.d.		Date: 11/21/2017
Emergency Contact Number:			
Comment:	Operator contact information posted on wellhead sign. 505-326-3753 number goes to voicemail for offices of D J Simmons.		
Corrective Action:			Date:
Good Housekeeping:			
Type	DEBRIS		
Comment:	Production related debris and trash scattered around location. Concrete cribbing in corner of location.		
Corrective Action:	Clean up and remove debris and trash to comply with Rule 603.f.		Date: 10/22/2017
Type	WEEDS		
Comment:	Production pad covered in weeds. Weeds are growing around fired production equipment.		
Corrective Action:	Remove weeds to comply with Rule 603.f.		Date: 10/02/2017
Type	UNUSED EQUIPMENT		
Comment:	Fence panels, gates, pump jack safety barrier, and other production related equipment piled around pump jack.		
Corrective Action:	Remove unused equipment to comply with Rule 603.f.		Date: 10/22/2017
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment: <input type="text"/>			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	TANK BATTERY		
Comment:	Steel T-Post and hog wire fencing.		
Corrective Action:			Date:
Equipment:			corrective date
Type: Prime Mover	# 1		

Comment:		Natural gas motor.		Date:	
Corrective Action:				Date:	
Type: Ancillary equipment	# 1				
Comment:		Telemetry equipment.		Date:	
Corrective Action:				Date:	
Type: Other	# 1				
Comment:		Lube oil tank.		Date:	
Corrective Action:				Date:	
Type: Pump Jack	# 1				
Comment:				Date:	
Corrective Action:				Date:	
Type: Other	# 1				
Comment:		Sound wall panels.		Date:	
Corrective Action:				Date:	
Type: Deadman # & Marked	# 2				
Comment:		Not all deadmen marked.		Date:	
Corrective Action:		Locate and mark all deadmen to comply with Rule 1003.a.		Date:	10/22/2017
Type: Ancillary equipment	# 1				
Comment:		Wellhead.		Date:	
Corrective Action:				Date:	
Type: Horizontal Heated Separator	# 1				
Comment:				Date:	
Corrective Action:				Date:	
Type: Flow Line	# 4				
Comment:		In use - 3" steel line from wellhead casing and tubing to separator inlet. All points co-located. In use - 1" steel line from wellhead casing to supply gas knock out at prime mover. All points co-located. In use - 3" steel line from separator outlet to gas meter inlet. All points co-located. In use - 1" steel line from separator oil dump to production tank. All points co-located.		Date:	
Corrective Action:				Date:	
Type: Gas Meter Run	# 1				
Comment:				Date:	
Corrective Action:				Date:	
Type: Bird Protectors	# 1				
Comment:				Date:	
Corrective Action:				Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	Open Top		
Comment: Above ground open top tank with expanded metal top and earthen berms. There is 2' 1" of fluids in tank at time of inspection. Tank is over half full.					

Corrective Action:		Date:	
--------------------	--	-------	--

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	UNKNOWN no capacity label.	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Insufficient	Base Insufficient	Inadequate
Comment: Berms have weeds growing on them and inside bermed area. Berms are compromised with animal burrows.				
Corrective Action: Repair or install berms or other secondary containment devices per Rule 605.a.(4).				Date: 10/22/2017

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		,
Comment: Above ground 300 BBL steel tank with earthen berms. There are 5' 1" of fluids in tank at time of inspection.					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	Label missing. Taken off data plate.	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Insufficient	Base Insufficient	Inadequate
Comment: Berms have weeds growing on them and inside bermed area. Berms are compromised with animal burrows.				
Corrective Action: Repair or install berms or other secondary containment devices per Rule 605.a.(4).				Date: 10/22/2017

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected FacilitiesFacility ID: 285440 Type: WELL API Number: 067-09196 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: SI - Review of electronic well file reflects that the last reported production was March 2015 with production numbers of 109/0. The well has been reported SI since April 2015 with last production report submitted June 2017. No current MIT on record or delinquent as required by Rule 326.

Corrective Action: Contact dnr_cogccengineering@state.co.us with resolution plan.

Date: 10/02/2017

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: Rural residential properties with dry land farming.**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? Pass

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? Pass

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? Pass

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? FailComment Not all deadmen marked.Corrective Action Locate and mark all deadmen to comply with Rule 1003.a.Date **10/22/2017**

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention	Fail	

Comment: [Oil lube tank with no spill prevention.](#)Corrective Action: [Install or repair required BMPs to comply with Rule 1002.f.](#)

Date: 10/22/2017

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401410152	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4256636
685303778	Inspection pictures.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4256633