

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/22/2017

Submitted Date:

09/27/2017

Document Number:

690100116

FIELD INSPECTION FORM

Loc ID 323610 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10459
Name of Operator: EXTRACTION OIL & GAS INC
Address: 370 17TH STREET SUITE 5300
City: DENVER State: CO Zip: 80202

Findings:

- 2 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Carlisle, Josh		jcarlisle@extractionog.com	
,		COGCCInspections@extracti onog.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
245472	WELL	PR	04/01/2017	GW	123-13267	DECHANT 1-19	EG

General Comment:

Engineering Integrity inspection performed on 9/22/17. Change of operator form 10 Doc # 401336150 was received on 07/11/2017. Details of observations made during this field inspection are available in the flowline section of this report. Photo's uploaded can be accessed via link(s) at the end of this report.

Inspected FacilitiesFacility ID: 245472 Type: WELL API Number: 123-13267 Status: PR Insp. Status: EG**Flowline**

#1	Type: Dump Line	1 of Lines	
<u>Flowline Description</u>			
Flowline Type: <u>Dump Line</u>	Size:	Material:	
Variance:	Age:	Contents:	
<u>Integrity Summary</u>			
Failures:	Spills:	Repairs Made:	
Coatings:	H2S:	Cathodic Protection:	
<u>Pressure Testing</u>			
Witnessed: <u>No</u>	Test Result: <u>Pass</u>	Charted: <u>Yes</u>	
<u>COGCC Rules (check all that apply)</u>			
<input type="checkbox"/> 1101. Installation and Reclamation	<input checked="" type="checkbox"/> 1102. Operations, Maintenance, and Repair	<input type="checkbox"/> 1103. Abandonment	
<u>Comment:</u>	Inspector met with Extraction lease operator Fred Buckholz on location. The produced water flowline and vault have been removed and are not scheduled to be replaced at this time. The crude oil dump line was pressure tested (for Integrity confirmation); test passed (chart attached).		
<u>Corrective Action:</u>			<u>Date:</u>

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690100128	Oil Dump Line Pressure Test Chart	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4262727
690100129	Battery/ signage (berms maintained)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4262728
690100130	Horizontal separator (berms maintained)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4262729