

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/22/2017

Submitted Date:

09/29/2017

Document Number:

690100114

FIELD INSPECTION FORM

Loc ID 320465 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10454
Name of Operator: PETROSHARE CORPORATION
Address: 9635 MAROON CIRCLE #400
City: ENGLEWOOD State: CO Zip: 80112

Findings:

3 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Powell, Harold	(918)-774-3120	hpowell@petrosharecorp.com	
, Engineering		dnr_cogccengineering@state.co.us	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Lloyd, Bill		blloyd@petrosharecorp.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203829	WELL	PR	04/01/2001	GW	001-09389	GUTHRIE 22-2	EG

General Comment:

The Actions Required listed on (EG) field inspection doc #690100099 performed on 09/07/2017 have been completed. Details are outlined in the equipment/ flowline and idle well sections of this report. Photos uploaded can be accessed via link(s) at end of report.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type				corrective date
Flow Line	# 0			
Comment:	Action Required Completed; Flowline risers (2) observed at facility/ adjacent to horizontal separators have been removed.			
Corrective Action:				Date: <input type="text"/>

Venting:

Yes/No			
Comment:			
Corrective Action:			Date: <input type="text"/>

Flaring:

Type		
Comment:		
Corrective Action:		Date: <input type="text"/>

Inspected Facilities

Facility ID: 203829 Type: WELL API Number: 001-09389 Status: PR Insp. Status: EG

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Action Required Completed; COGCC Engineering group contacted, form 6 intent to abandon doc #401398643 has been received by COGCC. Wellhead locked/ tagged out.

Corrective Action: Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690100133	Inactive flowline riser removed at (W) separator inlet	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4263372
690100134	Wellhead locked/ tagged out	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4263373
690100135	Inactive flowline riser removed at (E) separator inlet	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4263374