

Location

Overall Good:

Signs/Marker:			
Type	DRILLING/RECOMP		
Comment:	Rig signage at county road entrance location.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	Survey line around location.		
Corrective Action:		Date:	

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 250862 Type: WELL API Number: 123-18665 Status: PR Insp. Status: PA

Cement

Cement Contractor

Contractor Name: _____

Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____

Circulate to Surface: _____

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): _____

Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): 4300

Cement Volume (sx): 145 Sacks

Good Return During Job: YES

Cement Type: G

Comment: Witness tagging of plug at 3628. Calculated top was estimated at 3693
Company representative on location: Edgar

Corrective Action:

Date: _____

Workover

Comment: BASIC 1652

Corrective Action:

Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690000487	Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4264551