



**Inspected Facilities**

Facility ID: 237934 Type: WELL API Number: 121-10437 Status: PR Insp. Status: PA

**Cement**

Cement Contractor

Contractor Name: Excell

Contractor Phone: \_\_\_\_\_

Surface Casing

Cement Volume (sx): \_\_\_\_\_

Circulate to Surface: \_\_\_\_\_

Cement Fall Back: \_\_\_\_\_

Top Job, 1" Volume: \_\_\_\_\_

Intermediate Casing

Cement Volume (sxs): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Production Casing

Cement Volume (sx): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Plugging Operations

Depth Plugs(feet range): \_\_\_\_\_

Cement Volume (sx): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Cement Type: \_\_\_\_\_

Comment: During cut, cap and cover, cement was tagged at 95'.  
 Operator contacted cement truck to fill hole that arrived the next day.  
 Flowline was capped ~6' below ground surface at wellhead. Additional flowline to pit will be removed.  
 Submit Form 6 (S) within 30 days. Removed equipment within 90 days.  
 GPS of wellhead it 39.89612 and -102.88798.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688300393	Stelbar Price 9 wellhead sign	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4264918">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4264918</a>