

- Southern Ute 33 – 10; 15 - 3
- 05-067-08833



Photo 1: Wellhead sign.

- Southern Ute 33 – 10; 15 - 3
- 05-067-08833



Photo 2: Separation in E fill slope.

- Southern Ute 33 – 10; 15 - 3
- 05-067-08833



**Photo 3: Closer view of separation.**

- Southern Ute 33 – 10; 15 - 3
- 05-067-08833



**Photo 4: Collapse in E fill slope.**

- Southern Ute 33 – 10; 15 - 3
- 05-067-08833



**Photo 5: Erosion channel off E fill slope.**

- Southern Ute 33 – 10; 15 - 3
- 05-067-08833



**Photo 6: Erosion channel repair.**

- Southern Ute 33 – 10; 15 - 3
- 05-067-08833



**Photo 7: Repair in SE corner.**

- Southern Ute 33 – 10; 15 - 3
- 05-067-08833



**Photo 8: Closer view of repair in SE corner.**