

Final Reclamation Inspection

October 4, 2017

Operator: CHESAPEAKE OPERATING LLC- 16660

API: 05-123-34079

Weld County, CO

SWSE Section 2 T9N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: HUTCHISON 2-9-67 #1H
API: 05-123-34079



Google Earth imagery taken September 7, 2016 illustrating the ~0.9 mile access road and location that has not been reclaimed. Well was plugged December 21, 2012.

Inspection Photos
Location Name: HUTCHISON 2-9-67 #1H
API: 05-123-34079



Photo 1. Photo taken from the entrance of the location off CR110, facing North. Russian thistle growing throughout the access road portions of the road.



Photo 2. Photo taken from a portion of the access road, facing South. Russian thistle growing throughout the access road portions of the road, gravel still on access road, and access road has not been contoured or seeded.

Inspection Photos
Location Name: HUTCHISON 2-9-67 #1H
API: 05-123-34079



Photo 3. Photo taken from a portion of the access road at an intermittent stream crossing, facing North. Culverts need to be removed per Rule 1004.



Photo 4. Photo taken from another portion of the access road, facing East. Culverts need to be removed per Rule 1004.

Inspection Photos
Location Name: HUTCHISON 2-9-67 #1H
API: 05-123-34079



Photo 5. Photo taken from the entrance of the location, facing West. Culvert, cattle guards, and fence have all been left at location.



Photo 6. Photo taken from the entrance of the location, facing South.

Inspection Photos
Location Name: HUTCHISON 2-9-67 #1H
API: 05-123-34079



Photo 7. Photo taken from just beyond the gate shown in Photo 5, facing South. Russian thistle growth continues throughout access road.



Photo 8. Photo taken north of the well pad, facing Southeast. Photo illustrates the fill slope that indicates this location has never been reclaimed per Rule 1004 standards.

Inspection Photos
Location Name: HUTCHISON 2-9-67 #1H
API: 05-123-34079



Photo 9. Photo taken north of the well pad, facing Southeast. Refer to Photo 8 for the description of the observations.



Photo 10. Photo taken from the eastern well pad, facing North. Refer to Photo 8 for the description of the observations.

Inspection Photos
Location Name: HUTCHISON 2-9-67 #1H
API: 05-123-34079



Photo 11. Photo taken from the eastern well pad, facing South. Refer to Photo 8 for the description of the observations.



Photo 12. Photo taken from the southern location, facing West. Operator has not performed reclamation as cut slopes and gravel are evident throughout the location.

Inspection Photos
Location Name: HUTCHISON 2-9-67 #1H
API: 05-123-34079



Photo 13. Photo taken from the northwestern well pad, facing South. Refer to Photo 12 for the description of the observations.



Photo 14. Photo taken from the northwestern well pad, facing Southeast. Refer to Photo 12 for the description of the observations.

Inspection Photos
Location Name: HUTCHISON 2-9-67 #1H
API: 05-123-34079



Photo 15. Photo taken from the northwestern well pad, facing East. Refer to Photo 12 for the description of the observations.



Photo 16. Photo taken just north of the well pad, facing North. Photo illustrates the Russian thistle that is growing throughout the access road.