

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/26/2017

Submitted Date:

09/28/2017

Document Number:

687400244**FIELD INSPECTION FORM**

Loc ID 320251 Inspector Name: Kraich, Adam On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10110Name of Operator: GREAT WESTERN OPERATING COMPANY LLCAddress: 1801 BROADWAY #500City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**16 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspections@gwogco.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203231	WELL	PR	08/01/2013	OW	001-08740	ADAMS AGGREGATE 2	PR

General Comment:

Location				
Lease Road:				
Type	Access			
comment:	Road is shared with gravel pit access.			
Corrective Action	L			Date:
Type	Other			
comment:	Roads at battery are overgrown with weeds.			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:	Adequate			
Corrective Action:				Date:
Type	TANK LABELS/PLACARDS			
Comment:	Adequate			
Corrective Action:				Date:
Type	BATTERY			
Comment:	Adequate			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	Adequate			
Corrective Action:				Date: _____
Good Housekeeping:				
Type	WEEDS			
Comment:	Weeds are overgrown throughout location including berms and roads. See inspection photos.			
Corrective Action:	Comply with Rule 603.f .			Date: 10/09/2017
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	PUMP JACK			
Comment:	Half metal sheeting, half chainlink			
Corrective Action:				Date:
Type	LOCATION			
Comment:	Chainlink into location, shared gate with gravel pit and reservoir.			
Corrective Action:				Date:

Type	TANK BATTERY		
Comment:	4 strand barbed wire		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	4 strand barbed wire		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Natural gas fired engine		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	Conventional		
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment:	with shed		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	300 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
			Date:	

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 203231 Type: WELL API Number: 001-08740 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
	kraicha	09/28/2017

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401416730	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4262770
687400245	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4262665