

Inspection Photos
Location Name: Graefe 1
Facility ID: 317527

SW¼ NW¼ Section 26 Township 9 North Range 62 West



Photo 1: Oily soil in tank battery. Standing water is stormwater.



Photo 2: Produced water ASTs.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Graefe 1
Facility ID: 317527

SW¼ NW¼ Section 26 Township 9 North Range 62 West



Photo 3: Crude Oil ASTs.



Photo 4: Oily soil at pump adjacent flowlines and horizontal separator.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Graefe 1
Facility ID: 317527

SW¼ NW¼ Section 26 Township 9 North Range 62 West



Photo 5: Oily soil inside vertical treater building.



Photo 6: Oily soil inside horizontal treater shed.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Graefe 1
Facility ID: 317527

SW¼ NW¼ Section 26 Township 9 North Range 62 West



Photo 7: Oily soil at wellhead.



Photo 8: Weeds on location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Graefe 1
Facility ID: 317527

SW¼ NW¼ Section 26 Township 9 North Range 62 West



Photo 9: Unmarked deadman.



Photo 10: Unused pipe adjacent pumjack.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Graefe 1
Facility ID: 317527

SW¼ NW¼ Section 26 Township 9 North Range 62 West



Photo 11: Unused piping and weeds at tank battery.



Photo 12: Leaks inside injection pumphouse.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Graefe 1

Facility ID: 317527

SW¼ NW¼ Section 26 Township 9 North Range 62 West



Photo 13: Overview of location, weeds on location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources