

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/05/2017

Submitted Date:

10/05/2017

Document Number:

689300255**FIELD INSPECTION FORM**
 Loc ID 323018 Inspector Name: O'Donnell, Shaun On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1625 BROADWAY STE 2200City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**10 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|-------|--|---------|
| , | | NBL_DJBU_Inspections@NB LENERGY.COM | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 244649 | WELL | SI | 01/01/2017 | GW | 123-12444 | SCHANK 1 | SI |

General Comment:

LocationOverall Good: ☒

| | | | |
|----------------------|----------------------|-------|--|
| Signs/Marker: | | | |
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: _____

Good Housekeeping:

| | | | |
|--------------------|---|-------|------------|
| Type | WEEDS | | |
| Comment: | Actively growing weeds on location need to be controlled. See attached photos | | |
| Corrective Action: | Comply with Rule 603.f . | Date: | 10/15/2017 |

Overall Good: ☐**Spills:**

| | | | | |
|------|------|--------|--|--|
| Type | Area | Volume | | |
|------|------|--------|--|--|

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

| | | | |
|--------------------|-------------|-------|--|
| Type | LOCATION | | |
| Comment: | Barbed wire | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | Steel panel | | |
| Corrective Action: | | Date: | |

Equipment:

| | | | |
|-----------------------------------|-----|-------|-----------------|
| | | | corrective date |
| Type: Gas Meter Run | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Horizontal Heated Separator | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|-------------------------------|---|--|-------|
| Type: Plunger Lift | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Bird Protectors | # 2 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Flow Line | # 2 | | |
| Comment: | 1-2" steel riser marked deactivated southwest of crude oil tank 1-2" steel riser marked deactivated north of ECD | | |
| Corrective Action: | | | Date: |
| Type: Ancillary equipment | # 1 | | |
| Comment: | ECD knockout at crude oil tank | | |
| Corrective Action: | | | Date: |
| Type: Emission Control Device | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---------|----------|--------------|---------|--------|
| PRODUCED WATER | 1 | <50 BBLS | PBV CONCRETE | | , |
| Comment: | 48 BBLS | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|--|
| Condition | |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|---------------------------------|---------------------|---------------------|-------------|
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | Shares berm with crude oil tank | | | |
| Corrective Action: | | | | Date: |

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|-----------------------|
| CRUDE OIL | 1 | 300 BBLS | STEEL AST | | 40.360120,-104.745480 |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|----------|
| Condition | Adequate |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
|--------------------|----------|---------------------|---------------------|-------------|--|
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate | |
| Comment: | | | | | |
| Corrective Action: | | | | Date: | |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Inspected FacilitiesFacility ID: 244649 Type: WELL API Number: 123-12444 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: SI

Corrective Action: _____ Date: _____

BradenHeadComment: Bradenhead valve is exposed at surface

Corrective Action: _____ Date: _____

Environmental

Spill/Remediation:

Comment:

Corrective
Action:

Date:

Emission Control Burner (ECB): YES

Comment: Battery is shut in

Pilot: OFF

Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------|---|
| 689300256 | Inspection photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4268399 |