

Inspection Photos



Photo 1. Facing west along the former access road.

Inspection Photos



Photo 2. There are post and wire that remain at the east side of the location.

Inspection Photos



Photo 3. Facing west toward the location. The desirable vegetation along the eastern portion of the location has re-established.

Inspection Photos



Photo 4. West side of the location facing east. The desirable vegetation has not adequately established at the western portion of the location.

Inspection Photos



Photo 5. West side of the location facing northeast. The brown vegetation is undesirable weed growth (Kochia).

Inspection Photos



Photo 6. There is undesirable weed growth throughout the western portion of the location.

Inspection Photos



Photo 7. North side of the location facing southwest. This area does not have adequate desirable vegetation establishment.

Inspection Photos



Photo 8. Facing north off the location toward the undisturbed vegetation.