

Inspection Photos  
Location Name SP 431-14  
API: 05-045-19704



**Photo 1. BMP damaged or not maintained**



Inspection Photos  
Location Name SP 431-14  
API: 05-045-19704



**Photo 2. BMP damaged or not maintained**




Inspection Photos  
Location Name SP 431-14  
API: 05-045-19704



**Photo 3. Sediment migration from pad surface**



Inspection Photos  
Location Name SP 431-14  
API: 05-045-19704



**Photo 4. Sediment migration from pad surface**

Inspection Photos  
Location Name SP 431-14  
API: 05-045-19704



**Photo 5. Erosion on pad surface**





Inspection Photos  
Location Name SP 431-14  
API: 05-045-19704



**Photo 5. Cut slope not stabilized, debris and sediment moving onto pad**



Inspection Photos  
Location Name SP 431-14  
API: 05-045-19704



Photo 5. Sediment migration along lease road.

