

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/05/2017

Submitted Date:

10/06/2017

Document Number:

666803803**FIELD INSPECTION FORM**
 Loc ID 335374 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Elsener, Garrett		COGCC.inspections@caerus oilandgas.com	All Piceance inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
268667	WELL	PR	02/20/2004	GW	045-09285	GMR 21-8D (H21)	PR
271937	WELL	PR	09/14/2004	GW	045-09984	GMR 22-4A (H21)	PR
271938	WELL	PR	10/19/2004	GW	045-09983	GMR 21-2A (H21)	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Vertical Heated Separator

2

Comment: Corrective Action: Date:

Type: Plunger Lift

3

Comment: Corrective Action: Date:

Type: Gas Meter Run

1

Comment: Corrective Action: Date:

Type: Horizontal Heated Separator

1

Comment: Corrective Action: Date: **Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLS	STEEL AST		39.512646,-107.771774

Comment: Corrective Action: Date: **Paint**Condition Adequate Other (Content) Other (Capacity) Other (Type) **Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment: <input type="text"/>				
Corrective Action: <input type="text"/>				Date: <input type="text"/>

Inspected Facilities			
Facility ID: <u>268667</u>	Type: <u>WELL</u>	API Number: <u>045-09285</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
<u>Producing Well</u>			
Comment:	<u>Plunger lift</u>		
Corrective Action:		Date:	
Facility ID: <u>271937</u>	Type: <u>WELL</u>	API Number: <u>045-09984</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
<u>Producing Well</u>			
Comment:	<u>Plunger lift</u>		
Corrective Action:		Date:	
Facility ID: <u>271938</u>	Type: <u>WELL</u>	API Number: <u>045-09983</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
<u>Producing Well</u>			
Comment:	<u>Plunger lift</u>		
Corrective Action:		Date:	

Environmental	
Spill/Remediation:	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB): NO	
Comment:	
Pilot:	Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches	Pass			
Gravel	Pass					
		Gravel	Pass			
		Culverts	Pass			
Berms	Pass					
Seeding	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
666803804	caerus	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4269582