

## Inspection Photos



**Photo 1.** 2016 aerial image of the access road and location.

## Inspection Photos



**Photo 2.** View of the access road from the county road.



## Inspection Photos



**Photo 3.** Beginning of the access road.



## Inspection Photos



**Photo 4.** Facing southeast along the access road.



## Inspection Photos



**Photo 5.** Facing southeast along the access road. There are stormwater issues occurring in this area.



## Inspection Photos



**Photo 6.** Facing southeast, the access road begins to ascend the hillside.



## Inspection Photos



**Photo 7.** Facing southeast along the access road.



## Inspection Photos



**Photo 8.** Facing southeast along the access road. There is signs of potential sloughing along the road. Arrow points to 3.5 ft. shovel placed into the surface opening.



## Inspection Photos



**Photo 9.** Facing northwest where the access road turns and ascends up the hillside.



## Inspection Photos



**Photo 10.** Facing south where the access road continues to the bottom of the canyon. There are erosion issues occurring down the road.



## Inspection Photos



**Photo 11.** Facing northwest where the access road turns and ascends the hillside. There are signs of erosion occurring down the road.



## Inspection Photos



**Photo 13.** Facing northwest where the access road ascends the hillside. There are signs of erosion rilling occurring down the road.



## Inspection Photos



**Photo 13.** Facing southeast back down the access road. There is predominately undesirable vegetation along the fill slope.



## Inspection Photos



**Photo 14.** Facing northwest where the access road ascends the hillside. There are signs of erosion rilling occurring down the road.



## Inspection Photos



**Photo 15.** Facing northwest where the access road ascends the hillside. There are signs of erosion rilling occurring down the road.



## Inspection Photos



**Photo 16.** Facing back down the road. The cut slope is not adequately stabilized and there is erosion occurring down the road.



## Inspection Photos



**Photo 17.** Facing northwest along the access road.



## Inspection Photos



**Photo 18.** Facing back toward the southeast down the access road.



## Inspection Photos



**Photo 19.** Facing northwest where the access road ascends to the top of the hill where the well pad is located.



## Inspection Photos



**Photo 20.** Facing northwest toward the location.



## Inspection Photos



**Photo 21.** Facing northwest at the location.



## Inspection Photos



**Photo 22.** Facing east toward the fill slope of the location.



## Inspection Photos



**Photo 23.** West side of the location facing east.



## Inspection Photos



**Photo 24.** Facing east toward the cut slope.



## Inspection Photos



**Photo 25.** Facing northeast overlooking the location.