

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/04/2017

Submitted Date:

10/07/2017

Document Number:

680102272**FIELD INSPECTION FORM**Loc ID: 451937 Inspector Name: Colby, Lou On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10598Name of Operator: SANDRIDGE EXPLORATION & PRODUCTION LLCAddress: 123 ROBERT S KERR AVECity: OKLAHOMA CITY State: OK Zip: 73102**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
		sandridgeenvironmental@san dridgeenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
451937	LOCATION	AC	08/30/2017		-	Shiras CTB S11	RI

General Comment:

This is a Construction and Stormwater inspection. Form 42 (Notice of Construction) was Filed for this Location with start Date of 9/25/17. Conditions at time of Inspection were 40 degrees and Sunny. Contiguous Landscape has light Snow cover, elevation at Site is 8,154 ft.

Location ConstructionLocation ID: 451937 CDP: _____

Comment: Inspection was conducted after a significant precipitation event. Area had received heavy rainfall & Snow two days prior to Insp Date; Snow Melt was in process at time of Insp.

Corrective Action: _____ Date: _____

Form 2A COAs:

Comment: _____

Corrective Action: _____ Date: _____

Wildlife BMPs:Comment: Location is in SWH; Greater Sage Grouse.

Corrective Action: _____ Date: _____

Stormwater:

Erosion BMPs	Present	Other BMPs	Present
WADDLES	No		

Comments: Erosion BMPs: _____

Other BMPs: _____

Corrective Action: _____ Date: _____

	No		
Comments: Erosion BMPs: Access Road BMPs are not installed. Culverts are present but not installed at point where SW is collecting and needs relief to drainage.			
Other BMPs: 			
Corrective Action:		Date:	
SLOPE ROUGHENING	Yes		
Comments: Erosion BMPs: 			
Other BMPs: 			
Corrective Action:		Date:	
BERMS	Yes		
Comments: Erosion BMPs: Portion of Berms are not consolidated. loose Piles of Soil are potential Pollution sources.			
Other BMPs: 			
Corrective Action:		Date:	
DITCHES	Yes		
Comments: Erosion BMPs: 			
Other BMPs: 			
Corrective Action:		Date:	
Comment: Perimeter SW Controls are not sufficient for Location or Access Road. Refer to Photos attached. Operator has indicated that needed BMPs would be installed / repaired ASAP.			
Corrective Action: Install appropriate BMPs to comply with COGCC stormwater rules and prevent migration of sediment off location and Access Road. CA Dates given are immediate as Perimeter Controls should have been installed Prior to Construction & there is immediate threat to Surface Water Quality as Snow Melt & Sediment Migration is occurring.			Date: 10/11/2017

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Inspected FacilitiesFacility ID: 451937 Type: LOCATION API Number: - Status: AC Insp. Status: RI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
680102276	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4270653