

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/04/2017

Submitted Date:

10/09/2017

Document Number:

690100155**FIELD INSPECTION FORM**
 Loc ID 329859 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name       | Phone | Email                         | Comment |
|--------------------|-------|-------------------------------|---------|
| Schlagenhauf, Mark |       | mark.schlagenhauf@state.co.us |         |
| ,                  |       | cogccinspections@anadarko.com |         |
| Hazard, Ellice     |       | ellice.hazard@state.co.us     |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 250141      | WELL | PR     | 05/01/2010  | OW         | 123-17944 | GLENS VV 6-14 | EG          |

**General Comment:**

The Actions Required listed on (EG) field inspection doc #690100094 performed on 09/06/2017 have been completed. Details are outlined in the flowline section of this report. Photos uploaded can be accessed via link(s) at end of report.

**Inspected Facilities**Facility ID: 250141 Type: WELL API Number: 123-17944 Status: PR Insp. Status: EG**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: [COGCC/KMOG Operator Tolling Agreement addresses outstanding COGCC Rule 603.h, Rule 326 and Rule 319.b. compliance actions.](#)

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Flowline**

#1 Type: Well Site 1 of Lines

Flowline DescriptionFlowline Type: Well Site Size: 2" Material: Carbon SteelVariance: \_\_\_\_\_ Age: \_\_\_\_\_ Contents: MultiphaseIntegrity Summary

Failures: \_\_\_\_\_ Spills: \_\_\_\_\_ Repairs Made: \_\_\_\_\_

Coatings: \_\_\_\_\_ H2S: \_\_\_\_\_ Cathodic Protection: \_\_\_\_\_

Pressure Testing

Witnessed: \_\_\_\_\_ Test Result: \_\_\_\_\_ Charted: \_\_\_\_\_

COGCC Rules(check all that apply)☐ 1101. Installation and Reclamation ☐ 1102. Operations, Maintenance, and Repair ☒ 1103. AbandonmentComment: [Action Required Completed; Glens VV 6-14 flowline abandonment completed, operator emailed confirmation photos on 10/3/2017. The signage at horizontal separator has been changed accordingly. FIRR Resolution form Doc #401421135 has been approved.](#)

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description                        | URL   |
|--------------|------------------------------------|---|
| 690100160    | Signage at separator inlet changed | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4270684">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4270684</a> |