

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/05/2017

Submitted Date:

10/09/2017

Document Number:

690100157

FIELD INSPECTION FORM

Loc ID 323515 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 8840
Name of Operator: BLUE CHIP OIL INC
Address: 155 E BOARDWALK DR STE 400
City: FORT COLLINS State: CO Zip: 80525

Findings:

- 2 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
		bluechipoil@msn.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
245345	WELL	PR	01/01/2015	GW	123-13140	NORTH POU DRE 1	EG

General Comment:

Engineering Integrity Inspection performed on October 5th, 2017 in response to initial form 19 spill report Doc #401419071 received by COGCC on 10/03/2017 that outlines: Suspected soil contamination upon removal of produced water storage tank. Site has been shut in since 5/22/2017. Details of observations made during this field inspection are available in the flowline section of this report. Photo's uploaded can be accessed via link(s) at the end of this report.

Inspected Facilities

Facility ID: 245345 Type: WELL API Number: 123-13140 Status: PR Insp. Status: EG

Flowline

#1	Type:	of Lines
----	-------	----------

Flowline Description

Flowline Type: _____ Size: _____ Material: _____
 Variance: _____ Age: _____ Contents: _____

Integrity Summary

Failures: _____ Spills: _____ Repairs Made: _____
 Coatings: _____ H2S: _____ Cathodic Protection: _____

Pressure Testing

Witnessed: _____ Test Result: _____ Charted: _____

COGCC Rules(check all that apply)

1101. Installation and Reclamation 1102. Operations, Maintenance, and Repair 1103. Abandonment

Comment: The focus of this field inspection is on the abandonment of flowlines associated with this well/ location. COGCC inspector met with Blue Chip contract personnel on site (Mundt/ CGRS). Excavation and remediation activities are in progress. The well site flowline (between wellhead & separator) has been abandoned in place, flowline risers removed. The dump flowlines have been removed. A historically abandoned flowline was encountered in the open excavation, and is assumed to be an old dump line. The ends of this line were found/ identified; this line is being removed from the well site.

Corrective Action: _____

Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690100163	Excavation and historically abandoned flowline	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4270687
690100164	Excavation/ remediation looking North	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4270688