

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

10/05/2017

Submitted Date:

10/09/2017

Document Number:

690100158**FIELD INSPECTION FORM**
 Loc ID 327332 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 8840Name of Operator: BLUE CHIP OIL INCAddress: 155 E BOARDWALK DR STE 400City: FORT COLLINS State: CO Zip: 80525**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
,		bluechipoil@msn.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
246715	WELL	PR	04/08/2002	OW	123-14512	SLOAN 3	EG

**General Comment:**

Engineering Integrity Inspection performed on October 5th, 2017 in response to initial form 19 spill report Doc #401419004 received by COGCC on 10/03/2017 that outlines: Suspected soil contamination upon removal of produced water storage tank. Site has been shut in since 6/7/2017. Details of observations made during this field inspection are available in the flowline section of this report. Photo's uploaded can be accessed via link(s) at the end of this report.

**Inspected Facilities**

Facility ID: 246715 Type: WELL API Number: 123-14512 Status: PR Insp. Status: EG

**Flowline**

#1	Type:	of Lines	
<u>Flowline Description</u>			
Flowline Type:	Size:	Material:	
Variance:	Age:	Contents:	
<u>Integrity Summary</u>			
Failures:	Spills:	Repairs Made:	
Coatings:	H2S:	Cathodic Protection:	
<u>Pressure Testing</u>			
Witnessed:	Test Result:	Charted:	
<u>COGCC Rules(check all that apply)</u>			
<input type="checkbox"/> 1101. Installation and Reclamation <input type="checkbox"/> 1102. Operations, Maintenance, and Repair <input checked="" type="checkbox"/> 1103. Abandonment			
Comment:	The focus of this field inspection is on the abandonment of flowlines associated with this well/ location. Notice of flowlines abandoned doc #401336479 was filed with COGCC on 07/10/2017. Based on observations, the well site flowline (between wellhead & separator) has been abandoned in place, flowline risers removed. The dump flowlines have been removed from location. The equipment and tanks are in process of being removed from location. Excavation and remediation activities are in progress.		
Corrective Action:			Date:

**COGCC Comments**

Comment	User	Date
This well has been plugged and abandoned; Form 6 intent doc #401287740 filed 06/01/2017 (Replug By Other Operator/ Synergy Resources).	maclarej	10/09/2017
Note: There is a gas meter run/ gathering riser located on the north side of location.	maclarej	10/09/2017
The following COGCC final reclamation rule(s) may be applicable in future: COGCC Rule 1004. FINAL RECLAMATION OF WELL SITES AND ASSOCIATED PRODUCTION FACILITIES (partial description of rule) a. Well sites and associated production facilities. Upon the plugging and abandonment of a well, all pits, mouse and rat holes and cellars shall be backfilled. All debris, abandoned gathering line risers and flowline risers, and surface equipment shall be removed within three (3) months of plugging a well.		

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690100165	Tank battery/ PW vault removed	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4270689">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4270689</a>
690100166	Inactive meter run/ gathering riser	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4270690">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4270690</a>