

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/06/2017

Submitted Date:

10/10/2017

Document Number:

674200243**FIELD INSPECTION FORM**
 Loc ID 335664 Inspector Name: Gomez, Jason On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10633Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLCAddress: 1801 CALIFORNIA STREET #2500City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc.inspections@crestonepr.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
250886	WELL	PR	09/24/1997	GW	123-18689	VESSELS MINERALS 'E' 1	PA
278108	WELL	PR	05/24/2006	GW	123-23018	VESSELS 24-19	PA
278119	WELL	PR	05/24/2006	GW	123-23009	VESSELS 23-19	PA
411852	WELL	PR	07/28/2009	GW	123-30277	VESSELS MINERALS 4-6-19	SI
411854	WELL	PR	07/30/2009	GW	123-30278	VESSELS MINERALS 2-4-19	SI
411855	WELL	PR	07/26/2009	GW	123-30279	VESSELS MINERALS 14-19	SI

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	DRILLING/RECOMP		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	APPROX 25' MOBILE SOUND WALLS SURROUND LOCATION		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type	Field Flare		
Comment:	CONTROLLED WITH CHOKE SYSTEM		
Corrective Action:		Date:	

Inspected Facilities

Facility ID: <u>250886</u>	Type: <u>WELL</u>	API Number: <u>123-18689</u>	Status: <u>PR</u>	Insp. Status: <u>PA</u>
Facility ID: <u>278108</u>	Type: <u>WELL</u>	API Number: <u>123-23018</u>	Status: <u>PR</u>	Insp. Status: <u>PA</u>
Facility ID: <u>278119</u>	Type: <u>WELL</u>	API Number: <u>123-23009</u>	Status: <u>PR</u>	Insp. Status: <u>PA</u>
Facility ID: <u>411852</u>	Type: <u>WELL</u>	API Number: <u>123-30277</u>	Status: <u>PR</u>	Insp. Status: <u>SI</u>
Facility ID: <u>411854</u>	Type: <u>WELL</u>	API Number: <u>123-30278</u>	Status: <u>PR</u>	Insp. Status: <u>SI</u>
Facility ID: <u>411855</u>	Type: <u>WELL</u>	API Number: <u>123-30279</u>	Status: <u>PR</u>	Insp. Status: <u>SI</u>

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass	Vehicle Tracking	Pass	

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT