

Inspection Photos
Location Name: Stroh 24-12
API: 05-123-22367



Replaced produced water vault



Wellhead