

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/11/2017

Submitted Date:

10/11/2017

Document Number:

679903174**FIELD INSPECTION FORM**

Loc ID 324874 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 81480Name of Operator: THOMAS L SPRING LLCAddress: 7400 E ORCHARD RD STE 106-SCity: GREENWOOD State: CO Zip: 80111**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|---------------------------|------------------|---------|
| Springs, Tom | 303-771-1889 off/68710 | T1spring@aol.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 213353 | WELL | SI | 04/01/2017 | GW | 061-06715 | RUTH 1-25 | SI |

General Comment:

Location**Lease Road:**

| | | | |
|--------------------|---------------------------|-------|--|
| Type | Access | | |
| comment: | Trail through farm ground | | |
| Corrective Action: | | Date: | |

Overall Good: ☒**Signs/Marker:**

| | | | |
|--------------------|---------------------------|-------|--|
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Sticker on tank | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | Lease sign mounted to HGS | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

| | | |
|--------------------|--|-------------|
| Comment: | | |
| Corrective Action: | | Date: _____ |

Overall Good: ☒**Spills:**

| | | | | |
|------|------|--------|--|--|
| Type | Area | Volume | | |
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

| | | | | |
|-----------------------------|----------------------------------|-----------------------|------------|------------------|
| Inspected Facilities | | | | |
| Facility ID: 213353 | Type: WELL | API Number: 061-06715 | Status: SI | Insp. Status: SI |
| Producing Well | | | | |
| Comment: | Well is SI at time of inspection | | | |
| Corrective Action: | | | | Date: |

| |
|--|
| |
|--|

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

Comment: Access has been washed out. There are deep ruts on the north side of location. Repair access through farm ground to main access point around lake. Part of the access has been farmed over and planted to wheat.

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|--|---|
| 679903175 | Eroded access looking west | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4272192 |
| 679903176 | Erosion on north side of location looking east | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4272193 |