

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/11/2017

Submitted Date:

10/12/2017

Document Number:

690100168

FIELD INSPECTION FORM

Loc ID 336326 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

- 4 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
,		cogccinspections@anadarko.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
251857	WELL	PR	08/01/2014	GW	123-19662	TRAVELERS U 28-13DI	EG

General Comment:

Engineering Integrity Inspection performed on October 11th, 2017 in response to initial form 19 spill report Doc #401422863 received by COGCC on 10/09/2017 that outlines: During abandonment activities at the Travelers U 28-13 tank battery, historical petroleum hydrocarbon impacts were encountered beneath the partially-buried produced water vessel. Details of observations made during this field inspection are available in the flowline section of this report. Photo's uploaded can be accessed via link(s) at the end of this report.

Inspected Facilities

Facility ID: 251857 Type: WELL API Number: 123-19662 Status: PR Insp. Status: EG

Flowline

#1	Type:	of Lines
<u>Flowline Description</u>		
Flowline Type:	Size:	Material:
Variance:	Age:	Contents:
<u>Integrity Summary</u>		
Failures:	Spills:	Repairs Made:
Coatings:	H2S:	Cathodic Protection:
<u>Pressure Testing</u>		
Witnessed:	Test Result:	Charted:
<u>COGCC Rules(check all that apply)</u>		
<input type="checkbox"/> 1101. Installation and Reclamation <input type="checkbox"/> 1102. Operations, Maintenance, and Repair <input type="checkbox"/> 1103. Abandonment		
<u>Comment:</u>	Notice of flowlines abandoned doc #401342791 was filed with COGCC on 07/14/2017. There were no flowlines/ risers observed on location. Production tanks and equipment have been removed from well pad. Excavation/ remediation activities observed in progress.	
<u>Corrective Action:</u>		<u>Date:</u>

COGCC Comments

Comment	User	Date
This well has been plugged and abandoned; Form 6 intent doc #400976806 filed 01/22/2016; Field operations notice doc #401383047/ start of plugging operations filed on 08/22/2017.	maclarej	10/12/2017
Note: There is a gas meter run/ gathering riser located on the NW corner location.	maclarej	10/12/2017
The following COGCC final reclamation rule(s) may be applicable in future: COGCC Rule 1004. FINAL RECLAMATION OF WELL SITES AND ASSOCIATED PRODUCTION FACILITIES (partial description of rule) a. Well sites and associated production facilities. Upon the plugging and abandonment of a well, all pits, mouse and rat holes and cellars shall be backfilled. All debris, abandoned gathering line risers and flowline risers, and surface equipment shall be removed within three (3) months of plugging a well.		

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690100172	Signage at access road	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4272951
690100173	Plugged well below grade	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4272952
690100174	Meter run/ soil stockpile on NW corner location	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4272953