

Inspection Photos



Photo 1. Facing south at the location where pipe riser was removed.

Inspection Photos



Photo 2. South side of the location facing north.

Inspection Photos



Photo 3. Facing west at the location. The are bare areas that have not adequately re-established vegetation.

Inspection Photos



Photo 4. Facing east toward the surrounding undisturbed pasture.