

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

10/12/2017

Submitted Date:

10/16/2017

Document Number:

666803842**FIELD INSPECTION FORM**
 Loc ID 334829 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Elsener, Garrett		COGCC.inspections@caerus oilandgas.com	All Piceance inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211177	WELL	PR	12/30/1994	GW	045-06936	BENZEL 36-16	PR
266184	WELL	PR	06/11/2004	GW	045-09116	BJM 31-13A (P36)	PR
266185	WELL	PR	02/20/2004	GW	045-09117	BENZEL 36-15A (P36)	PR
269296	WELL	PR	01/22/2005	GW	045-09347	BENZEL 36-9C (P36)	PR
269298	WELL	PR	02/25/2008	GW	045-09346	BJM 31-13D (P36)	PR
269595	WELL	PR	02/14/2004	GW	045-09385	BENZEL 36-15A1 (P36)	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type UNUSED EQUIPMENT

Comment: Flow lines

Corrective Action:

Date:

Overall Good: ☒**Spills:**

Type Area Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Gas Meter Run # 1

Comment:

Corrective Action:

Date:

Type: Horizontal Heated Separator # 2

Comment:

Corrective Action:

Date:

Type: Vertical Heated Separator # 4

Comment:

Corrective Action:

Date:

Type: Plunger Lift # 6

Comment:

Corrective Action:

Date:

Tanks and Berms:

Contents # Capacity Type Tank ID SE GPS

CONDENSATE 1 300 BBLs STEEL AST

Comment: Centralized battery

Corrective Action:

Date:

Paint

Condition Adequate

Other (Content)

Other (Capacity)

Other (Type)

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	500 BBLs	STEEL AST		39.477331,-107.716451
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	211177	Type:	WELL	API Number:	045-06936	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger Lift								
Corrective Action:						Date:			
Facility ID:	266184	Type:	WELL	API Number:	045-09116	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger Lift								
Corrective Action:						Date:			
Facility ID:	266185	Type:	WELL	API Number:	045-09117	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger Lift								
Corrective Action:						Date:			
Facility ID:	269296	Type:	WELL	API Number:	045-09347	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger Lift								
Corrective Action:						Date:			
Facility ID:	269298	Type:	WELL	API Number:	045-09346	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger Lift								
Corrective Action:						Date:			
Facility ID:	269595	Type:	WELL	API Number:	045-09385	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger Lift								
Corrective Action:						Date:			

Environmental

Spill/Remediation:

Comment:

Corrective
Action:

Date:

Emission Control Burner (ECB): NO

Comment:

Pilot:

Wildlife Protection Devices (fired vessels):

YES

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Seeding	Pass					
		Gravel	Pass			
Gravel	Pass					
		Culverts	Pass			
Berms	Pass					
Ditches	Pass					
		Ditches	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
666803847	caerus	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4275544