

Inspection Photos

10/13/2017

Operator: PAPE OILFIELD SERVICE INC - 67165

Location ID: 317172

Inspection Doc. Number: 682502705

Washington County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: PAPE OILFIELD SERVICE INC - 67165
Location ID: 317172



Photo 1: Photo taken from the south end of the location, facing north. Photo shows the starting point of the disturbance transect.



Photo 2: Photo of the 50th point of the disturbance transect, facing west. Photo shows vegetation over the reclamation area.

Inspection Photos
Operator: PAPE OILFIELD SERVICE INC - 67165
Location ID: 317172



Photo 3: Photo of the 50th point of the disturbance transect, facing east. Photo shows vegetation over the reclamation area.



Photo 4: Photo of the 50th point of the disturbance transect. Photo shows vegetation over the reclamation area.

Inspection Photos
Operator: PAPE OILFIELD SERVICE INC - 67165
Location ID: 317172



Photo 5: Photo taken from the north end of the location, facing south. Photo shows the end point of the disturbance transect.



Photo 6: Photo taken from the adjacent reference area, facing west. Photo shows the starting point of the reference transect.

Inspection Photos
Operator: PAPE OILFIELD SERVICE INC - 67165
Location ID: 317172



Photo 7: Photo of the 50th point of the reference transect, facing south. Photo shows vegetation over the reference area.



Photo 8: Photo of the 50th point of the reference transect, facing north. Photo shows vegetation over the reference area.

Inspection Photos
Operator: PAPE OILFIELD SERVICE INC - 67165
Location ID: 317172



Photo 9: Photo of the 50th point of the reference transect. Photo shows vegetation over the reference area.



Photo 10: Photo taken from the adjacent reference area, facing west. Photo shows the end point of the reference transect.

Inspection Photos

Operator: PAPE OILFIELD SERVICE INC - 67165

Location ID: 317172



Photo 11: Photo taken from the location. Inspector had tested the site for compaction concerns. Photo shows inspector was only able to penetrate the first couple of inches of topsoil with relative ease.



Photo 12: Inspector tested the site for soil compaction, photo shows horizontal plate formations in the top inches of soil. This is an indication of soil compaction.

Inspection Photos

Operator: PAPE OILFIELD SERVICE INC - 67165

Location ID: 317172



Photo 13: Photo taken from the reference area. Inspector had tested the soil in the reference area for comparison. Photo shows inspector was able to easily penetrate the topsoil.



Photo 14: Photo of the reference area topsoil to compare to the disturbance area.