

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Rod iron		
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 238640 Type: WELL API Number: 123-05503 Status: IJ Insp. Status: AC

Underground Injection Control

UIC Violation: _____ Maximum Injection Pressure: _____

UIC Routine

Inj./Tube: Pressure or inches of Hg _____ Previous Test Pressure _____ MPP _____
 (e.g. 30 psig or -30" Hg) Inj Zone: LYNS
 TC: Pressure or inches of Hg _____ Previous Test Pressure _____ Last MIT: 07/22/2015
 Brhd: Pressure or inches of Hg _____ Previous Test Pressure _____ AnnMTReq: _____

Comment: _____

Corrective Action: _____ Date: _____

Method of Injection: _____

Test Type: Verification of Repairs Tbg psi: 0 Csg psi: 1500 BH psi: 0

Insp. Status: Fail Leak Type: Casing

Comment: Pressured up to 1500#, would not hold pressure on casing. Possible packer leaking. Talked to company man, will get back over here with a work over rig. When finished, will come back out and retest. Pressure test failed

Corrective Action: _____ Date: _____

BradenHead

Comment: Bradenhead valve is exposed at surface

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<u>MIT test failed. Great Western is going to get work over rig to service well. Will contact us when finished to retest.</u>	odonnells	10/17/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689300270	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4277166