

Construction and Stormwater Inspection

October 12, 2017

Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC -#8960

Location ID: 450213

Weld County, CO

SESE Section 34 T4N R63W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Mustang /44-34 Pad
Location ID: 450213



Photo 1. Google Earth aerial imagery taken on June 14, 2016. A disturbance area of 4.75 acres was mapped on 10/12/2017 using a Trimble Juno 3B handheld device (red line). Appears the Operator has overbuilt the location by 1.25 acres (36% overbuilt) per the approved Form 2A .

Inspection Photos
Location Name: Mustang /44-34 Pad
Location ID: 450213



Photo 2. Photo taken from the eastern location, facing South. Operator has installed a ditch and berm around the entire location perimeter. Portions of the berm BMP have not been properly compacted and have been left unconsolidated.



Photo 3. Photo taken from the northeastern location, facing West. See comments under Photo 2.

Inspection Photos
Location Name: Mustang /44-34 Pad
Location ID: 450213



Photo 4. Photo taken from the northwestern location, facing West. See comments under Photo 2.



Photo 5. Photo taken from the western location, facing South. See comments under Photo 2.

Inspection Photos
Location Name: Mustang /44-34 Pad
Location ID: 450213



Photo 6. Photo taken from the southern location, facing East. See comments under Photo 2.