

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

10/16/2017

Submitted Date:

10/18/2017

Document Number:

674200299**FIELD INSPECTION FORM**
 Loc ID 434526 Inspector Name: Gomez, Jason On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10633Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLCAddress: 1801 CALIFORNIA STREET #2500City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
		megan.adamczyk@state.co.us	
		cogcc.inspections@crestonepr.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
434525	WELL	DG	11/23/2014	SI	123-38225	Pratt 4G-29H-P168	WO
434527	WELL	DG	07/24/2017	LO	123-38226	Pratt 4D-29H-P168	WO
434528	WELL	DG	07/21/2017	LO	123-38227	Pratt 4F-29H-P168	WO
434529	WELL	DG	07/22/2017	LO	123-38228	Pratt 4E-29H-P168	WO
434530	WELL	DG	07/27/2017	LO	123-38229	Pratt 4B-29H-P168	WO
434733	WELL	DG	07/25/2017	LO	123-38301	Pratt 4C-29H-P168	WO

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type

LOCATION

Comment:

APPROX 32'S SOUND WALLS SURROUND LOCATION FOR SOUND AND LIGHT MITIGATION

Corrective Action:

Date:

Equipment:

corrective date

Type: Ancillary equipment

#

Comment:

2 FRAC PUMPS AND 2 WIRE LINE UNITS AND 2 CRANES ON LOCATION

Corrective Action:

Date:

Venting:

Yes/No

NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: <u>434525</u>	Type: <u>WELL</u>	API Number: <u>123-38225</u>	Status: <u>DG</u>	Insp. Status: <u>WO</u>
Facility ID: <u>434527</u>	Type: <u>WELL</u>	API Number: <u>123-38226</u>	Status: <u>DG</u>	Insp. Status: <u>WO</u>
Facility ID: <u>434528</u>	Type: <u>WELL</u>	API Number: <u>123-38227</u>	Status: <u>DG</u>	Insp. Status: <u>WO</u>
Facility ID: <u>434529</u>	Type: <u>WELL</u>	API Number: <u>123-38228</u>	Status: <u>DG</u>	Insp. Status: <u>WO</u>
Facility ID: <u>434530</u>	Type: <u>WELL</u>	API Number: <u>123-38229</u>	Status: <u>DG</u>	Insp. Status: <u>WO</u>
Facility ID: <u>434733</u>	Type: <u>WELL</u>	API Number: <u>123-38301</u>	Status: <u>DG</u>	Insp. Status: <u>WO</u>

Complaint

Comment:

Complaint Received 10-16- 2017

Field Inspector Assigned: Jason E. Gomez

Complaint Received:

Date: 10-16-2017 Time 0800Hrs

Contacted by Complaint Specialist per Complaint Response forms

Date: 10-16-2017

Well Number#: Location #: 434375

Inspection Document #: 674200297

Nature of complaint: Noise/Odors

Field Inspector Actions:

On 10-16-2017, I was contacted by complaint specialist Megan Adamczyk in reference to several complaints received for 10-13-2017 THRU 10-16-2017 by the COGCC about noise/odors occurring in the Erie area south of the Crestone Peak Resources, Waste Connection frac pad.

On 10-16-2017 at approx 2200 hrs , I performed a complete site inspection of the Waste Connection and Pratt location and the neighborhoods south of the frac pad. At the time of inspection, I observed 2 Liberty Services frac crew performing frac operations on the location for Crestone Peak Resources. I reviewed location records, which did not show any abnormal frac operations at the time of the complaints. I also reviewed the 3rd party sound data and the town of Erie's sound data information which did not show any exceedance of noise levels. I performed a sound study approx 25' from the residence of one of the complaints which was located in 1800 block of Crestview Ln in Erie. (See attached sound study for results.) The only odors detected on location were exhaust fumes from equipment on location. No odors other than exhaust fumes were detected off location at the time of the inspection. At the time of the inspection all lighting on location appeared to be pointed toward the ground and center of location.

All information reviewed and site inspection information were submitted to the COGCC for further review.

No violations of COGCC rules were observed at the time of the inspection

Corrective Action:		Date:	
--------------------	--	-------	--

<u>Well Stimulation</u>	
Stimulation Company: <u>LIBERTY WELL SERVICES</u>	Stimulation Type: <u>HYDRAULIC FRAC</u>
<u>Observation:</u>	Other: _____
Maximum Casing Recorded: _____ PSI	Tubing: _____
Surface: _____	Intermediate: _____
Production: _____	Instantaneous Shut-In Pressure (ISIP) <u>3500</u>
Bradenhead Psi: _____	Frac Flow Back: Fluid: _____ Gas: _____
<u>Comment:</u> _____	
Corrective Action: _____	Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Vehicle Tracking	Pass	
Compaction	Pass	Compaction	Pass	Covering Materials	Pass	
					Pass	

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674200300	Crestview Residence	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4278840