

Inspection Photos



Photo 1. 2015 aerial image shows access road and location disturbance still exists.

Inspection Photos



Photo 2. Center of the location facing north. The desirable vegetation has not re-established.

Inspection Photos



Photo 3. Center of the location facing west.

Inspection Photos



Photo 4. Center of the location facing south.

Inspection Photos



Photo 5. Center of the location facing east.

Inspection Photos




Photo 6. View of groundcover at the location. There is predominately undesirable weeds (*Kochia* sp.) throughout the location.

Inspection Photos



Photo 7. Facing southeast at the location. A 100ft. tape measure shows a portion of the location with no vegetation establishment.

Inspection Photos



Photo 8. Facing south off the location toward the undisturbed vegetation.