

## Inspection Photos



**Photo 1.** Facing east along the former access road which is still noticeable.



## Inspection Photos



**Photo 2.** Center of the location facing north. The desirable vegetation has not adequately re-established.



## Inspection Photos



**Photo 3.** Center of the location facing west. The dark-brown vegetation is predominately undesirable vegetation (*Kochia* sp., *R. thistle*).



## Inspection Photos



**Photo 4.** Center of the location facing south.



## Inspection Photos



**Photo 5.** Center of the location facing east. The desirable vegetation has not adequately re-established.



## Inspection Photos



**Photo 6.** Facing north at the location. A 100 ft. tape measure shows a portion of the location which vegetation has not re-established.



## Inspection Photos



**Photo 7.** View of groundcover at the location. The desirable vegetation has not adequately re-established.



## Inspection Photos



**Photo 8.** Facing west off the location toward the undisturbed vegetation.