

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/22/2017

Submitted Date:

10/13/2017

Document Number:

688000083**FIELD INSPECTION FORM**

Loc ID 313870 Inspector Name: YOUNG, ROB On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 95620Name of Operator: WESTERN OPERATING COMPANYAddress: 1165 DELAWARE STREET #200City: DENVER State: CO Zip: 80204**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
JAMES, STEVEN D	(303) 893-2438	steve@westernoperating.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
116794	PIT	AC			-	AMBROSE CUNNINGHAM 42-25	EI
226609	WELL	PR	09/05/1975	OW	087-07346	AMBROSE-CUNNINGHAM 42-25	EI

General Comment:

Environmental inspection related to Rem #1549. Photograph the corrective actions and submit them on a FIRR once completed.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
Comment:						
Corrective Action:					Date:	

Paint

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				Inadequate
Comment:	Animal burrows in tank battery berm and erosion of berm material onto surrounding rangeland.			
Corrective Action:	Fill in burrows, maintain berms.			Date: 10/27/2017

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	116794	Type:	PIT	API Number:	-	Status:	AC	Insp. Status:	EI
Facility ID:	226609	Type:	WELL	API Number:	087-07346	Status:	PR	Insp. Status:	EI

Environmental**Spills/Releases:**

Type of Spill: OIL

Estimated Spill Volume: _____

Comment: Absorbent pads have been installed at the pumping unit and wellhead. A small amount of lube oil and crude oil have impacted surface soils.

Corrective Action: Continue to use absorbent pads and scrape up and properly dispose of oil impacted soil.

Date: 10/27/2017

Reportable: _____

GPS: Lat _____

Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat _____ Long _____

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

Spill/Remediation:

Comment: Historic Rem #1549 - Impala Resources LLC, 6/17/2002 associated with tank battery spill. Google Earth aerial photographs and visual inspection indicate likely landfarming area east of the tank battery has been successfully revegetated and the remediation project will be closed.

Corrective Action: _____

Date: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____

Wildlife Protection Devices (fired vessels): _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401429125	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4273950
688000084	Location photographs	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4273945
688000085	Wellhead photographs	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4273946