

# Construction and Stormwater Inspection

October 24, 2017

Operator: LONGS PEAK RESOURCES LLC- #10611

Location ID: 452516

Weld County, CO

SESE Section 31 T12N R66W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources


Inspection Photos  
Location Name: Oxnard East /0607-8CH  
Location ID: 452516



**Photo 1.** Photo taken from the entrance of location, facing East. Ditch and berm BMP installed around the entire perimeter of location. Berm BMP has been left unconsolidated which is not a proper functioning BMP, as unconsolidated material would be susceptible to wind and water erosion.

**Photo 2.** Photo taken from the entrance of location, facing West. See comments under Photo 1.

Inspection Photos  
Location Name: Oxnard East /0607-8CH  
Location ID: 452516



**Photo 3.** Photo taken from the southeastern location, facing North. Appears to be significant amount of space between the well pad and topsoil stockpile. Appears the Operator could have stored the topsoil stockpile closer to the well pad to minimize the total disturbance area.



**Photo 4.** Photo taken from the southeast location, facing North. See comments under Photo 1.

Inspection Photos  
Location Name: Oxnard East /0607-8CH  
Location ID: 452516



**Photo 5.** Photo taken from the eastern location, facing North. Appears topsoil has been salvaged and stored along the eastern perimeter of the location.



**Photo 6.** Photo taken from the northeast location, facing West. See comments under Photo 1.

Inspection Photos  
Location Name: Oxnard East /0607-8CH  
Location ID: 452516



**Photo 7.** Photo taken from the northwest location, facing South. See comments under Photo 1.



**Photo 8.** Photo taken from the western location, facing South. See comments under Photo 1.