

# Inspection Photos

10/23/2017

Operator: CM PRODUCTION LLC - 10352

Location ID: 312244

Inspection Doc. Number: 682502725

Logan County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC



**Photo 1:** Photo taken from the northeast corner of the location, facing south. Photos 1-3 show an overview of the location and interim areas. Interim areas on the southeast end of the location appear to be adequately vegetated.



**Photo 2:** Photo taken from the northeast corner of the location, facing southeast. Red colored plants seen in photo appear to be an Aster species, not undesirable weedy plant vegetation.



Inspection Photos  
Operator: CM PRODUCTION LLC - 10352  
Location ID: 312244



**Photo 3:** Photo taken from the northeast corner of the location, facing southwest



**Photo 4:** Photo taken from the north end of the location, facing northwest. The slopes on the north end show sign of erosion degradation.





**Photo 5:** Photo taken from the northwest corner of the location, facing east. Photos 5-7 show an overview of the location and interim areas.



**Photo 6:** Photo taken from the northwest corner of the location, facing east. Note: there appears to be areas leading from the anchors towards the well ~5-6 feet in width where vegetation does not appear to be uniform. This is a common occurrence observed on multiple CM Production locations in the area.



Inspection Photos  
Operator: CM PRODUCTION LLC - 10352  
Location ID: 312244



**Photo 7:** Photo taken from the northwest corner of the location, facing southeast. Vegetation on the southwest end of the location appears to have established adequately.



**Photo 8:** Photo taken from the north end of the location, facing south. Photo shows well/pump unit.





**Photo 9:** Photo taken from the southwest end of the location. Photo shows operator either discarded concrete debris off the location, or had attempted to utilize concrete as rip-rap.



**Photo 10:** Photo taken from the southwest end of the location, facing southeast. Photo shows erosion degradation that has formed, possibly due to stormwater runoff from the location.





**Photo 11:** Photo taken from the west end of the pump unit. Photo shows dark discolored soil that can be found around the unit, as well as inside.



**Photo 12:** Photo taken from the southeast end of the location. Photo shows cable debris observed on the interim area.





**Photo 13:** Photo taken from the southeast end of the location. Photo shows cable debris observed on the interim area.



**Photo 14:** Photo taken from a drainage to the immediate east of the well. Photo shows drainage has become inundated with Canada thistle. Though inspector was unable to observe the noxious weed on location, due to the proximity of the weeds, it possible that thistle does exist on site.