

**Inspection Photos**  
**Location Name: Behring #1**  
**API: 05-123-05198**



**Photo 1: Location, looking W**



**Photo 2: Wellhead, looking NW**



**Inspection Photos**  
**Location Name: Behring #1**  
**API: 05-123-05198**



**Photo from prior inspection for comparison**



**Photo 3: Unused pipe S of pit excavation**



**Inspection Photos**  
**Location Name: Behring #1**  
**API: 05-123-05198**



**Photo from prior inspection for comparison**



**Photo 4: Stained soil in engine house**

**Inspection Photos**  
**Location Name: Behring #1**  
**API: 05-123-05198**



**Photo from prior inspection for comparison**



**Photo 5: Stained soil at truck loadout**

**Inspection Photos**  
**Location Name: Behring #1**  
**API: 05-123-05198**



**Photo from R Allison's inspection for comparison**



**Photo 6: Pit excavation**

**Inspection Photos**  
**Location Name: Behring #1**  
**API: 05-123-05198**



**Photo from R Allison's inspection for comparison**



**Photo 7: Land farm, looking W**



**Inspection Photos**  
**Location Name: Behring #1**  
**API: 05-123-05198**



**Photo from R Allison's inspection for comparison**



**Photo 8: Burrows, weeds in berms**

Inspection Photos  
Location Name: Behring #1  
API: 05-123-05198



Photo from R Allison's inspection for comparison



Photo 9: Labels on tanks, rusted production tank, weeds along berms

Inspection Photos  
Location Name: Behring #1  
API: 05-123-05198




Photo from R Allison's inspection for comparison



Photo 10: Stained soil at wellhead

Inspection Photos  
Location Name: Behring #1  
API: 05-123-05198



Photo 11: Stained soil around engine house



Photo 12: Open produced water tank

**Inspection Photos**  
**Location Name: Behring #1**  
**API: 05-123-05198**



**Photo 13: Weeds along berm**



**Photo 14: Weeds around heater treater**

**Inspection Photos**  
**Location Name: Behring #1**  
**API: 05-123-05198**



**Photo 15: Debris, risers at pit excavation**