



Photo 1. View of the project area from the northwestern corner of the working area facing center.



Photo 2. View of the northern portion of the project area from the northwestern corner of the working area facing eastward.



Photo 3. View of the western portion of the project area from the northwestern corner of the working area facing southward. Revegetation is progressing within the outer disturbance areas and comprised of species such as western wheatgrass (*Pascopyrum smithii*). Blue frac tanks in the southwestern portion of the working area do not appear to be in use and need to be removed.



Photo 4. View of what appears to be frac sand in the southern portion of the working area.



Photo 5. View of pipe segment in the northwestern portion of the project area.





Photo 6. View of the southern edge of the project area from the southwestern corner of the working area facing eastward. Berms have recently been installed and seeded.