



Photo 1. View of the project area from the northwestern corner of the working area facing center.





Photo 2. View of the western portion of the project area from the northwestern corner of the working area facing southward. Revegetation is largely comprised of grazed grasses and rubber rabbitbrush (*Chrysothamnus nauseosus*).



Photo 3. View of the eastern cut-slope. The slope is not stabilized, as evidenced by overhanging vegetation at the top of the slope, and fallen pinyon tree, where eroding soil is exposing roots and resulting in sloughing.





Photo 4. View of weeds around equipment that need to be removed.