



Photo 1. View of the project area from the northwestern corner of the project area facing center.



Photo 2. View of the northern portion of the project area from the northwestern corner of the working area facing eastward. Revegetation is well established with grasses such as western wheatgrass (*Pascopyrum smithii*), and brome grass (*Bromus* sp.).



Photo 3. View of the western portion of the project area from the northwestern corner of the working area facing southward.



Photo 4. View of unused equipment and debris within the northeastern corner of the working area.



Photo 5. View of rock check dams along the access road that are full of sediment and need maintenance.



Photo 6. View of erosion that is occurring where concentrated stormwater exits a black pipe diversion from the southeastern edge of the well pad to a silt trap that is located upstream from a culvert adjacent to the lease road.