

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/19/2017

Submitted Date:

10/19/2017

Document Number:

689300290**FIELD INSPECTION FORM**Loc ID 332943 Inspector Name: O'Donnell, Shaun On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**17 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email                         | Comment |
|--------------|-------|-------------------------------|---------|
| ,            |       | COGCCinspections@Anadarko.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 277475      | WELL | PR     | 06/13/2005  | OW         | 123-22931 | ZEILER 9-7    | SI          |
| 280432      | WELL | PR     | 06/01/2016  | GW         | 123-23274 | ZEILER 15-7   | SI          |
| 280434      | WELL | PR     | 08/16/2006  | GW         | 123-23273 | ZEILER 10-7   | SI          |
| 284467      | WELL | PR     | 08/17/2006  | GW         | 123-23817 | ZEILER 16-7   | SI          |

**General Comment:**

**Location**Overall Good: ☒

|                      |                      |       |  |
|----------------------|----------------------|-------|--|
| <b>Signs/Marker:</b> |                      |       |  |
| Type                 | BATTERY              |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | WELLHEAD             |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | TANK LABELS/PLACARDS |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |

Emergency Contact Number:

Comment: [Adequate](#)

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

|                    |   |       |                            |
|--------------------|---|-------|----------------------------|
| Type               | UNUSED EQUIPMENT  |       |                            |
| Comment:           | <a href="#">Unused methanol tank and fencing at Zeiler 15-7 wellhead needs to be removed. See attached photos</a> |       |                            |
| Corrective Action: | <a href="#">Comply with Rule 603.f .</a>  | Date: | <a href="#">01/19/2018</a> |

Overall Good: ☐

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

|                    |                            |       |  |
|--------------------|----------------------------|-------|--|
| Type               | TANK BATTERY               |       |  |
| Comment:           | <a href="#">Chain link</a> |       |  |
| Corrective Action: |                            | Date: |  |
| Type               | WELLHEAD                   |       |  |
| Comment:           | <a href="#">Chain link</a> |       |  |
| Corrective Action: |                            | Date: |  |
| Type               | IGNITOR/COMBUSTOR          |       |  |
| Comment:           | <a href="#">Chain link</a> |       |  |
| Corrective Action: |                            | Date: |  |
| Type               | SEPARATOR                  |       |  |
| Comment:           | <a href="#">Chain link</a> |       |  |
| Corrective Action: |                            | Date: |  |

|                                   |  |  |                 |
|-----------------------------------|--|--|-----------------|
| <b>Equipment:</b>                 |  |  | corrective date |
| Type: Pig Station                 | # 1  |  |                 |
| Comment:                          |  |  |                 |
| Corrective Action:                |  |  | Date:           |
| Type: Horizontal Heated Separator | # 4  |  |                 |
| Comment:                          |  |  |                 |
| Corrective Action:                |  |  | Date:           |
| Type: Ancillary equipment         | # 2  |  |                 |
| Comment:                          | 2-ECD knockouts. 1 at tanks, 1 at ECD  |  |                 |
| Corrective Action:                |  |  | Date:           |
| Type: Gas Meter Run               | # 1  |  |                 |
| Comment:                          |  |  |                 |
| Corrective Action:                |  |  | Date:           |
| Type: Emission Control Device     | # 1  |  |                 |
| Comment:                          | ECD line from tanks to ECD is pinned open at ECD with a piece of wire. See attached photos |  |                 |
| Corrective Action:                |  |  | Date:           |
| Type: Bird Protectors             | # 5  |  |                 |
| Comment:                          |  |  |                 |
| Corrective Action:                |  |  | Date:           |
| Type: Plunger Lift                | # 4  |  |                 |
| Comment:                          |  |  |                 |
| Corrective Action:                |  |  | Date:           |

**Tanks and Berms:**

| Contents           | # | Capacity | Type           | Tank ID | SE GPS |
|--------------------|---|----------|----------------|---------|--------|
| PRODUCED WATER     | 1 | 100 BBLS | PBV FIBERGLASS |         | ,      |
| Comment:           |   |          |                |         |        |
| Corrective Action: |   |          |                |         | Date:  |

**Paint**

|                  |  |
|------------------|--|
| Condition        |  |
| Other (Content)  |  |
| Other (Capacity) |  |
| Other (Type)     |  |

**Berms**

| Type               | Capacity                         | Permeability (Wall) | Permeability (Base) | Maintenance |                       |
|--------------------|----------------------------------|---------------------|---------------------|-------------|-----------------------|
| Metal              | Adequate                         | Walls Sufficient    | Base Sufficient     | Adequate    |                       |
| Comment:           | Shares berm with crude oil tanks |                     |                     |             |                       |
| Corrective Action: |                                  |                     |                     | Date:       |                       |
| Contents           | #                                | Capacity            | Type                | Tank ID     | SE GPS                |
| CRUDE OIL          | 3                                | 300 BBLS            | STEEL AST           |             | 40.413060,-104.926380 |

|                    |  |       |
|--------------------|--|-------|
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

|                    |          |                     |                     |             |
|--------------------|----------|---------------------|---------------------|-------------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Metal              | Adequate | Walls Sufficent     | Base Sufficent      | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

**Venting:**

|                    |  |       |
|--------------------|--|-------|
| Yes/No             |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Flaring:**

|                    |       |
|--------------------|-------|
| Type               |       |
| Comment:           |       |
| Corrective Action: | Date: |

**Inspected Facilities**

Facility ID: 277475 Type: WELL API Number: 123-22931 Status: PR Insp. Status: SI

**Idle Well**

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: SI. No recorded production since August 2016

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Comment: Bradenhead valve is exposed at surface

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 280432 Type: WELL API Number: 123-23274 Status: PR Insp. Status: SI

**Idle Well**

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: SI. No recorded production since November 2015

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Comment: Bradenhead valve is exposed at surface

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 280434 Type: WELL API Number: 123-23273 Status: PR Insp. Status: SI

**Idle Well**

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: SI. No recorded production since August 2016

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Comment: Bradenhead valve is exposed at surface

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 284467 Type: WELL API Number: 123-23817 Status: PR Insp. Status: SI

**Idle Well**

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: SI. No recorded production since December 2015

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Comment: Bradenhead valve is exposed at surface

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

| Environmental                      |  |
|------------------------------------|--|
| <b>Spill/Remediation:</b>          |  |
| Comment:                           |  |
| Corrective Action:                 | Date:  |
| Emission Control Burner (ECB): YES |  |
| Comment:                           | Battery is shut in                               |
| Pilot: OFF                         | Wildlife Protection Devices (fired vessels): YES |

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 |                         |                       |               |                          |         |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 401435903    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4279641">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4279641</a> |
| 689300291    | Inspection photos    | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4279636">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4279636</a> |