

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/17/2017

Submitted Date:

10/26/2017

Document Number:

681700928

FIELD INSPECTION FORM

Loc ID 418908 Inspector Name: Arauza, Steven On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10112
Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC
Address: 5057 KELLER SPRINGS RD STE 650
City: ADDISON State: TX Zip: 75001

Findings:

- 6 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
,		dnr_cogccengineering@state.co.us	
,		regulatory@foundationenergy.com	All Inspections
Leonard, Mike		mike.leonard@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
418910	WELL	PR	05/13/2011	OW	123-32065	WICKSTROM 6-12	EI

General Comment:

[COGCC environmental inspection of wellhead only. Refer to Field Inspection Report #681700927 for conditions at shared production facility.](#)

Location			
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Well sign located at NE end of horizontal separator. Operator information is beginning to flake off. See photos.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>		Date: _____
Good Housekeeping:			
Type	WEEDS		
Comment:	Wind-blown weeds accumulating beneath horizontal separator. See photos.		
Corrective Action:	Comply with Rule 603.f .		Date: <u>11/05/2017</u>
Type	UNUSED EQUIPMENT		
Comment:	Horizontal separator has uncapped 1" flowline leading to riser on west side of wellhead.		
Corrective Action:	Comply with Rule 603.f .		Date: <u>01/26/2017</u>
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:	<input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
			corrective date
Type: Flow Line	# 1		
Comment:	NOT IN USE: Uncapped 1" flowline daylights from south end of horizontal separator to wellhead. See photos.		
Corrective Action:	Contact the Engineering Integrity section to discuss flowline abandonment requirements per Rule 1103. Along with the rule, the COGCC Operator Guidance, Rules 1101, 1102, and 1103: Flowline Guidance 1101 and 1102 guidance document can provide further details. Contact dnr_cogccengineering@state.co.us with resolution plan.		Date: <u>11/05/2017</u>
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
Venting:			
Yes/No			
Comment:			
Corrective Action:			Date:
Flaring:			
Type			
Comment:			

Corrective Action:

Date:

Inspected FacilitiesFacility ID: 418910 Type: WELL API Number: 123-32065 Status: PR Insp. Status: EI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
681700944	Well sign at unused horizontal separator.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4285183
681700945	Wellhead with plunger lift.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4285184
681700946	1" flowlines on west side of wellhead.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4285185
681700947	Weeds.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4285186
681700948	Wellhead from south.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4285187