

Inspection Photos
Location Name: Marick #1061-41
API: 05-123-30239



Photo 1: Location, looking SW



Photo 2: Wellhead, looking S

Inspection Photos
Location Name: Marick #1061-41
API: 05-123-30239



Photo 3: Stained soil at wellhead



Photo 4: Risers at ECD



Inspection Photos
Location Name: Marick #1061-41
API: 05-123-30239



Photo 5: Risers in treater house



Photo 6: Riser next to tank battery