

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/19/2017

Submitted Date:

10/23/2017

Document Number:

685303902

FIELD INSPECTION FORM

Loc ID 325354 Inspector Name: St John, William (Cal) On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 74500
Name of Operator: REYNOLDS* NOEL
Address: BOX 356
City: FLORA VISTA State: NM Zip: 87415

Findings:

- 9 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	COGCC

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214628	WELL	SI	03/01/1993	GW	067-06232	ESTER 1	SI

General Comment:

[See link at end of report for path to downloadable pictures.](#)

This is an orphan well inspection with emphasis on critical maintenance and abandonment. No previous corrective actions performed, corrective actions are still required.

With no current operator this well inspection included portions of May 2017 Flowline NTO to mark and inventory flowline risers. Due to location conditions and with no operator to provide assistance this inventory is informational only and may not identify all flowlines and risers.

Location

Lease Road:			
Type	Access		
comment:	No corrective action completed. Task will need to be generated to repair road in order to gain access for any work at well site.		
Corrective ActionL		Date:	

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?


Equipment:			corrective date
Type: Deadman # & Marked	# 2		
Comment:	Located (2) deadmen.		
Corrective Action:	Locate and mark all deadmen.	Date:	11/23/2017
Type: Ancillary equipment	# 1		
Comment:	Electrical service equipment.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellhead.		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Power pole and meter.		
Corrective Action:		Date:	
Type: Flow Line	# 1		
Comment:	In use - 3" line from wellhead. (B) point is unknown.		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	



Inspected FacilitiesFacility ID: 214628 Type: WELL API Number: 067-06232 Status: SI Insp. Status: SI**COGCC Comments**

Comment	User	Date
Tasks will likely include access road repair, P&A of well, Electrical service equipment removal, flowline removal/abandonment, and site clean up. Pit on location may require impacted material removal, possible sampling and analysis? TBD by Enviro. Additional finding of (2) rig anchors will require locate and removal of all anchors. Possible removal of power pole and meter that were run to location. Initial reclamation work on access road and location will be needed when all other work is completed.	stjohnw	10/23/2017

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401438563	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4281959
685303909	Inspection pictures.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4281956