

Construction and Stormwater Inspection

October 25, 2017

Operator: EXTRACTION OIL & GAS INC - #10459

Location ID: 426721

Weld County, CO

NENE Section 35 T7N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Hergert /35-D Facility
Location ID: 426721



Photo 1. Overview photo taken from the eastern location, facing South. Topsoil salvaged and stored along the eastern perimeter of the location.



Photo 2. Overview photo taken from the eastern location, facing Southwest. See comments under Photo 1.

Inspection Photos
Location Name: Hergert /35-D Facility
Location ID: 426721



Photo 3. Overview photo taken from the eastern location, facing West. See comments under Photo 1.



Photo 4. Overview photo taken from the eastern location, facing Northwest. See comments under Photo 1.

Inspection Photos
Location Name: Hergert /35-D Facility
Location ID: 426721



Photo 5. Photo taken from the eastern location, facing South. No stormwater and erosion control BMPs observed along the outer perimeter of stockpile.



Photo 6. Photo taken from the southeastern location, facing West. No stormwater and erosion control BMPs observed along this portion of the location. Operator plans to install ditch that will be directed to the sediment basin which has already been constructed.

Inspection Photos
Location Name: Hergert /35-D Facility
Location ID: 426721



Photo 7. Photo taken from the southwestern location, facing West. Silt fence BMP has been installed along the southwest, west, and northwest perimeter of location. Fill slopes need to be stabilized.



Photo 8. Photo taken from the southwestern location, facing North. Sediment basin has been constructed in conjunction with a silt fence BMP.

Inspection Photos
Location Name: Hergert /35-D Facility
Location ID: 426721



Photo 9. Photo taken from the southwestern location, facing East. See comments under Photo 8.



Photo 10. Photo taken from the outfall area of the sediment basin, facing East.

Inspection Photos
Location Name: Hergert /35-D Facility
Location ID: 426721



Photo 11. Photo taken from the western location, facing North. Silt fence BMP in need of maintenance.



Photo 12. Photo taken from the northern location, facing East. See comments under Photo 6.