

Inspection Photos



Photo 1. Facing northeast at the beginning of the former access road.

Inspection Photos



Photo 2. Facing northeast further along the former access road.

Inspection Photos



Photo 3. There are areas along the access road that gravel remains and soils are compacted.

Inspection Photos



Photo 4. Facing northeast further along the former access road.

Inspection Photos



Photo 5. Facing north toward the location.

Inspection Photos



Photo 6. Facing south at the location. There is some desirable vegetation establishment at the location.

Inspection Photos



Photo 7. West side of the location facing south. There is predominately undesirable vegetation at this side of the location.

Inspection Photos



Photo 8. West side of the location facing east.

Inspection Photos



Photo 9. Facing south toward the surrounding undisturbed pasture.