

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/30/2017

Submitted Date:

10/30/2017

Document Number:

674200313**FIELD INSPECTION FORM**
 Loc ID 434526 Inspector Name: Gomez, Jason On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10633Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLCAddress: 1801 CALIFORNIA STREET #2500City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
		Cogcc.inspections@crestone pr.com	
		megan.adamczyk@state.co.u s	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
434525	WELL	DG	11/23/2014	SI	123-38225	Pratt 4G-29H-P168	WO
434527	WELL	DG	07/24/2017	LO	123-38226	Pratt 4D-29H-P168	WO
434528	WELL	DG	07/21/2017	LO	123-38227	Pratt 4F-29H-P168	WO
434529	WELL	DG	07/22/2017	LO	123-38228	Pratt 4E-29H-P168	WO
434530	WELL	DG	07/27/2017	LO	123-38229	Pratt 4B-29H-P168	WO
434733	WELL	DG	07/25/2017	LO	123-38301	Pratt 4C-29H-P168	WO

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	DRILLING/RECOMP		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	APPROX 32' SPUND WALLS FOR LIGHT AND SOUND MITIGATION		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Ancillary equipment	#		
Comment:	1 COIL TUBING UNIT 1 CRANE		
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type	Field Flare		
Comment:	USED FOR VOCS FROM DRILL OUT		
Corrective Action:		Date:	

Inspected Facilities

Facility ID: <u>434525</u>	Type: <u>WELL</u>	API Number: <u>123-38225</u>	Status: <u>DG</u>	Insp. Status: <u>WO</u>
Facility ID: <u>434527</u>	Type: <u>WELL</u>	API Number: <u>123-38226</u>	Status: <u>DG</u>	Insp. Status: <u>WO</u>
Facility ID: <u>434528</u>	Type: <u>WELL</u>	API Number: <u>123-38227</u>	Status: <u>DG</u>	Insp. Status: <u>WO</u>
Facility ID: <u>434529</u>	Type: <u>WELL</u>	API Number: <u>123-38228</u>	Status: <u>DG</u>	Insp. Status: <u>WO</u>
Facility ID: <u>434530</u>	Type: <u>WELL</u>	API Number: <u>123-38229</u>	Status: <u>DG</u>	Insp. Status: <u>WO</u>
Facility ID: <u>434733</u>	Type: <u>WELL</u>	API Number: <u>123-38301</u>	Status: <u>DG</u>	Insp. Status: <u>WO</u>

Complaint

Comment: Well Number#: Location #: 434375/434526

Inspection Document #: 674200309/674200313

Nature of complaint: Noise/Odors

Field Inspector Actions:

On 10-30-2017, I was contacted by complaint specialist Megan Adamczyk in reference to several complaints received for 10-29-2017 and 10-30-2017 by the COGCC about noise/odors occurring in the Erie area south of the Crestone Peak Resources, Waste Connection frac pad.

On 10-30-2017 at approx 1200 hrs I performed a complete site inspection of the Waste Connection and Pratt location and the neighborhoods south of the locations. At the time of inspection, I observed 1 work over rig performing drill out operations on the waste connection location and 1 coil tubing unit performing drill out operations on the Pratt location for Crestone Peak Resources. I reviewed location records, which did not show any abnormal flow back operations at the time of the complaints. I also reviewed the 3rd party sound data and the town of Erie's sound data information which did not show any exceedance of noise levels.

At the time of the inspection I observed closed tanks being used for the flow back process and a filed flare being used to flare off any VOCS at both location. At the time of the inspection all lighting on location appeared to be pointed toward the ground and center of location. As part of the inspection I checked the area of the complaints for odors and at the time of the inspection I did not detect any odors off location.

All information reviewed and site inspection information were submitted to the COGCC for further review.

Corrective Action:

Date:

CompletionOperation: DrilloutDate Flowback: 10/30/2017

Contractor:

Comment:

Corrective Action:

Date:

Environmental

Spill/Remediation:

Comment:

Corrective
Action:

Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON

Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	
Gravel	Pass	Gravel	Pass	Vehicle Tracking	Pass	

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT