

Inspection Photos



Photo 1. Facing northwest toward the location.

Inspection Photos



Photo 2. There are areas of the location that are covered with wood mulch.

Inspection Photos



Photo 3. Some of the areas where there is wood mulch appear to have compacted soils. There is minimal vegetation establishment in these areas.

Inspection Photos



Photo 4. Facing south along the west side of the location.

Inspection Photos



Photo 5. Northwest side of the location facing east.

Inspection Photos



Photo 6. Northeast side of the location facing southwest.

Inspection Photos



Photo 7. East side of the location facing west.