

Inspection Photos



Photo 1. Facing east toward the location.

Inspection Photos



Photo 2. There is wood mulch applied to the soil surface.

Inspection Photos



Photo 3. Facing toward the east cut slope.

Inspection Photos



Photo 4. Facing west at the location.

Inspection Photos



Photo 5. Facing toward the northeast side of the location. There is signs that stormwater has displaced the wood mulch.

Inspection Photos



Photo 6. Facing west along the cut slope. A berm has been placed at the edge of the pad.

Inspection Photos



Photo 7. The plastic netting debris remains and has not been removed.

Inspection Photos



Photo 8. Facing toward the fill slope. There is signs of erosion occurring off the fill slope.

Inspection Photos



Photo 9. Facing southeast along the fill slope. Wood mulch has been applied along the fill slope.