

Inspection Photos



Photo 1. Facing northwest toward the location.

Inspection Photos



Photo 2. Facing southwest along the south side of the location. There is some undesirable weed debris and some desirable vegetation growth in this area.

Inspection Photos



Photo 3. There is wood straw mulch applied to bare areas of the location.

Inspection Photos



Photo 4. West side of the location facing east.

Inspection Photos



Photo 5. Facing southeast at the location.