

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/25/2017

Submitted Date:

10/31/2017

Document Number:

680102339

**FIELD INSPECTION FORM**

Loc ID 451456 Inspector Name: Colby, Lou On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**  
OGCC Operator Number: 10598  
Name of Operator: SANDRIDGE EXPLORATION & PRODUCTION LLC  
Address: 123 ROBERT S KERR AVE  
City: OKLAHOMA CITY State: OK Zip: 73102

**Findings:**

- 8 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
		sandridgeenvironmental@sandridgeenergy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
451455	WELL	XX	07/24/2017		057-06601	Mallard 0780 1-15H22	CI

**General Comment:**

This is a Construction and Stormwater Inspection, a Follow Up to Insp Doc#680102274 dated 10/4/17. Form 42 : NOTICE OF CONSTRUCTION: was Filed for this Site, Start Date 9/18/17. Conditions at time of Inspection were Sunny skies, windy at 67 degrees F. Elevation at Site is 8,111 ft.

**Location Construction**

Location ID: 451456 CDP: \_\_\_\_\_

**Comment:** Site has dried out since previous Inspection. Pad is compacted & based. The only construction activity at time of Inspection were preparations to install Wier at South West Corner of location. it appears that the majority of SW concerns from previous inspection have been addressed.

Corrective Action: \_\_\_\_\_ **Date:** \_\_\_\_\_

**Form 2A COAs:**

**Comment:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_ **Date:** \_\_\_\_\_

**Wildlife BMPs:**

**Comment:** Location is within SWH (Greater Sage Grouse) & is bordered on the East by the Arapaho National Wildlife Refuge.

Corrective Action: \_\_\_\_\_ **Date:** \_\_\_\_\_

**Stormwater:**

Erosion BMPs	Present	Other BMPs	Present
--------------	---------	------------	---------

MATS	Yes				
Comments: Erosion BMPs: <span style="color:blue;">Matting has been installed under area of Location Pad.</span>					
Other BMPs: <input type="text"/>					
Corrective Action: _____ Date: _____					
BERMS	Yes				
Comments: Erosion BMPs: <span style="color:blue;">Berm Compromised at SE corner of Pad has been repaired.</span>					
Other BMPs: <input type="text"/>					
Corrective Action: _____ Date: _____					
WADDLES	Yes				
Comments: Erosion BMPs: <span style="color:blue;">Wattles are installed around three sides of Location perimeter. Since snow melt Wattle installation is visible. Many areas of Wattles do not appear to be properly installed per Good Engineering Practices. Refer to Photos attached for detail of failed installation.</span>					
Other BMPs: <input type="text"/>					
Corrective Action: <span style="color:red;">Install or repair required BMPs per Rule 1002.f</span> Date: <span style="color:red;">11/30/2017</span>					
		Self Inspection		Yes	
Comments: Erosion BMPs: <span style="color:blue;">Operator indicated that South Entrance to Pad in low lying flood prone area may not be incorporated into final construction plans. See Photos Attached.</span>					
Other BMPs: <input type="text"/>					
Corrective Action: _____ Date: _____					
BERMS	Yes				
Comments: Erosion BMPs: <span style="color:blue;">Compromised Berm at NW Corner by Entry &amp; Fence that allows sediment Run on has not been repaired.</span>					
Other BMPs: <input type="text"/>					
Corrective Action: <span style="color:red;">Install or repair required BMPs per Rule 1002.f Operator indicated repair would be completed within 24 hours.</span> Date: <span style="color:red;">11/07/2017</span>					

**Comment:**

**Corrective Action:**  **Date:** \_\_\_\_\_

**On Site Inspection (305):**

Surface Owner Contact Information:  
 Name: \_\_\_\_\_ Address: \_\_\_\_\_  
 Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:  
 Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_  
 Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:  
 Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

**Inspected Facilities**

Facility ID: 451455 Type: WELL API Number: 057-06601 Status: XX Insp. Status: CI

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
680102340	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4289190">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4289190</a>