

Location			
Lease Road:			
Type	Main		
comment:	Lease road from entrance to battery has been repaired.		
Corrective Action	L		Date:
Type	Access		
comment:	Access road from battery to wellhead has been repaired		
Corrective Action	L		Date:

Overall Good:

Signs/Marker:			
Type	CONTAINERS		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:			
Type	WEEDS		
Comment:	Weeds on access road from battery to wellhead have been controlled		
Corrective Action:			Date:

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	SEPARATOR		
Comment:	Steel wire		
Corrective Action:			Date:

Type	WELLHEAD		
Comment:	Steel panel		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Steel wire		
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		
Comment:	Steel panel		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 265556 Type: WELL API Number: 123-21260 Status: TA Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Well is configured to produce, not producing at time of inspection

Corrective Action: _____ Date: _____

BradenHead

Comment: Bradenhead valve is exposed at surface

Corrective Action: _____ Date: _____

Environmental

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment: [Location erosion and lease road erosion issues have been addressed.](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
This is a follow up inspection in reference to Doc #689300300, FIR Doc #401446232. Lease road, access road, location erosion issues and weed issues have been addressed and corrected.	odonnells	11/01/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689300377	Operator submitted photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4291320