

Inspection Photos
Location Name: Argo 33-16
API: 05-081-07089



Photo 1. Surface of cement plug.



Photo 2. Surface of cement plug.

Inspection Photos
Location Name: Argo 33-16
API: 05-081-07089



Photo 3. Surface of cement plugs.



Photo 4. Backfilled area.

Inspection Photos
Location Name: Argo 33-16
API: 05-081-07089



Photo 5. Overview of location taken from southwest corner facing northeast.



Photo 6. Overview of location taken at entrance facing west.